


For dual-controller device

Note: Firstly, make sure your dual-controller device deploy in correct mode. As dual-controller device have two controllers, each controller have an IP separately , and we also need create a resource IP , so before you upgrade for the dual-controller device , let it work in dual-controller mode. You can check the Cluster interface in the 2004 page shown as below.



It's only allow to upgrade when device CVR status is **working**. So the right step should be

1. Login resource ip to check CVR service ([https://IP \(resource\):2004](https://IP (resource):2004)) .Make sure the CVR service status is **Working**.
2. Then you need to upgrade in two controller separately, login in [https://IP \(controller A\):2004](https://IP (controller A):2004) and [https://IP \(controller B\):2004](https://IP (controller B):2004); Do the upgrade operation in these two controller physical ip.



238-4 Firmware Package:


File Name	Time	File Type	Size
0storos-201711211501-Fix_CVRService_For_Mars-CVR2.3.X-915.bin	2020/11/19 13:38	VLC media file (.bin)	66 KB
1storos-202104191403-B_FW-Multi_V2.32sp3-915.bin	2021/4/20 15:10	VLC media file (.bin)	37,758 KB
2storos-202104151014-B_OS-N51745_CVR238sp1-915.bin	2021/4/19 09:42	VLC media file (.bin)	31,017 KB
3storos-201804091424-C_OS-StorOSManager_EN-915.bin	2021/4/19 09:42	VLC media file (.bin)	5,154 KB
4storos-202103040943-B_OS-rm_clearom.php-915.bin	2021/4/19 09:42	VLC media file (.bin)	53 KB
5storos-202106101422-B-CVR_238-4_Oversea_Main_Release-915.bin	2021/6/10 14:26	VLC media file (.bin)	40,185 KB
6storos-202106101428-B-CVR_238-4_Oversea_Hiklib_Release-915....	2021/6/10 14:28	VLC media file (.bin)	14,368 KB
7storos-202104261359-B-CVR_TO-EN-STD-VERSION-915.bin	2021/4/26 14:04	VLC media file (.bin)	4,743 KB

Steps:

Step1: Upgrade **storos-201711211501-Fix_CVRService_For_Mars-CVR2.3.X-915.bin** (Special for dual controller device) in controller A, then do same operation in controller B


Controller A:

Please wait several minutes until it shows below tips




Controller B:


Please wait several minutes until it shows below tips



Step2: Upgrade **1storos-202104191403-B_FW-Multi_V2.32sp3-915.bin** in controller A **Controller A:**

Please wait 3 minutes after it shows below tips, and this is a combined package, please enter the upgrade log interface to double check if all the patches upgrade success or not.





Step3: **2storos-202104151014-B_OS-N51745_CVR238sp1-915.bin**

Step4: **3storos-201804091424-C_OS-StorOSManager_EN-915.bin**

Step5: **4storos-202103040943-B_OS-rm_clearodom.php-915.bin**


Step6: **5storos-202106101422-B-CVR_238-4_Oversea_Main_Release-915.bin**

Step7: **6storos-202106101428-B-CVR_238-4_Oversea_Hiklib_Release-915.bin**

Step8: **7storos-202104261359-B-CVR_TO-EN-STD-VERSION-915.bin**

Step8: then do same step2、step3、...、step7、step8 in controller B

Step9: Reboot the controller A and controller B



HIKVISION DS-A82024D management

Intelligent, individual, economic and reliable data storage.

Log in to the System: Basic Management

User Name: web_admin

Password: |

Mode: Advanced Mode

Enter

HIKVISION DS-A82024D
System Version:Hybrid_SAN V2.3.8-4 Device Serial No.:77550000

First Choice for Security Professionals

HIKVISION Technical Support