

Turbo HD DVR v3.4.82_Build170427 Release Notes (2016-05-05)

Firmware Basic Information	Firmware Version:	V3.4.82_Build170427
	SDK Version:	V5.2.6.25_build20170104
	Play Library (PlayCtrl.dll)	6.0.0.4
	player	7.3.2.63
	Web version	V4.0.1 build 170118
	Client version	V2.05.06.07 build20170210

Reason of Upgrade

Fix some issues. This version is only suitable for DS-71/7200HGHI-Fx, DS-71/72/73/8100HQHI-Fx/N, DS-72/73/76/81/9000HUHI-Fx/N. Add some new functions, modify some functions, enhance products quality and meet customers' requirements.

Main update

Modified functions

- i. Add the "Upload Picture to Cloud" option to the **Linkage Method** of Alarm Input on webpage.

The screenshot shows the HIKVISION web interface for configuring an Alarm Input. The 'Configuration' tab is active, and the 'Alarm Input' sub-tab is selected. The 'Linkage Method' section is highlighted with a red box, and the 'Upload Pictures to Cloud' option is checked and also highlighted with a red box.

Normal Linkage	Trigger Alarm Output	Trigger Channel
<input type="checkbox"/> Audible Warning	<input type="checkbox"/> A->1	<input type="checkbox"/> A1
<input type="checkbox"/> Send Email	<input type="checkbox"/> A->2	<input type="checkbox"/> A2
<input type="checkbox"/> Notify Surveillance Center	<input type="checkbox"/> A->3	<input type="checkbox"/> A3
<input type="checkbox"/> Full Screen Monitoring	<input type="checkbox"/> A->4	<input type="checkbox"/> A4
<input checked="" type="checkbox"/> Upload Pictures to Cloud		<input type="checkbox"/> A5
		<input type="checkbox"/> A6

- ii. Fixed the issue that there is some probability of rebooting on DS-7316HUHI-F4/N.
- iii. On this version, UPnP function is not enabled as default.
- iv. Fixed the issue that there is no audio output on the live view of 15th and 16th channel of DS-7216HUH-F/N.

Related product list:

-F/N Series Turbo HD DVR	DS-7104HQHI-F1/N、DS-7108HQHI-F1/N、DS-7116HQHI-F1/N
	DS-7204HQHI-F1/N、DS-7208HQHI-F1/N、DS-7208HQHI-F2/N
	DS-7216HQHI-F1/N、DS-7216HQHI-F2/N
	DS-7304HQHI-F4/N、DS-7308HQHI-F4/N、DS-7316HQHI-F4/N
	DS-8104HQHI-F8/N、DS-8108HQHI-F8/N、DS-8116HQHI-F8/N
	DS-7104HGHI-F1、DS-7108HGHI-F1、DS-7116HGHI-F1
	DS-7204HGHI-F1、DS-7208HGHI-F1、DS-7208HGHI-F2
	DS-7216HGHI-F1、DS-7216HGHI-F2
	DS-7204HUHI-F1/N、DS-7208HUHI-F1/N、DS-7208HUHI-F2/N
	DS-7216HUHI-F1/N、DS-7216HUHI-F2/N
	DS-7604HUHI-F1/N、DS-7608HUHI-F2/N、DS-7216HUHI-F2/N
	DS-7304HUHI-F4/N、DS-7308HUHI-F4/N、DS-7316HUHI-F4/N
	DS-8104HUHI-F8/N、DS-8108HUHI-F8/N、DS-8116HUHI-F8/N
	DS-9004HUHI-F8/N、DS-9008HUHI-F8/N、DS-9016HUHI-F8/N

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.