KD9203 Firmware

V2.2.37_220316 Release Note

(2022-03-20)

Device Model	DS-KD9203-E6、 DS-KD9203-FE6、 DS-KD9203-TE6、 DS-
	KD9203-FTE6
Firmware Version	V2.2.37_220316
iVMS-4200 Version	Late version
Hik-Connect APP	Late version

Fix:

1、 Fix the issue that the fails to log in when the language other than English is selected .

KD9203 Firmware V2.2.37_211125 Release Note (2021-11-29)

Device Model	DS-KD9203-E6、 DS-KD9203-FE6、 DS-KD9203-TE6、 DS-
	KD9203-FTE6
Firmware Version	V2.2.37_211125
iVMS-4200 Version	Late version
Hik-Connect APP	Late version

Fix:

Modified bugs:

- 1. When Door Station call Indoor Station by "Outer Door Station" mode (with protocol 2.0), there is no massage record in Indoor Station.
- 2. The device will be rebooted caused by switching Portuguese.

KD9203 Firmware


V2.2.37_210812 Release Note

(2021-08-12)

Device Model	DS-KD9203-E6、 DS-KD9203-FE6、 DS-KD9203-TE6、 DS-
	KD9203-FTE6
Firmware Version	V2.2.37_210812
iVMS-4200 Version	Late version
Hik-Connect APP	4.13.1 or above

Modify

1、 HiK-Connect is disabled and Verification code is empty by default.



Face Recognize Door Station Firmware


V2.0.0_210120 Release Note

(2021-02-01)


Device Model	DS-KD9203-E6、DS-KD9203-FE6
	DS-KD9203-TE6、DS-KD9203-FTE6
Firmware Version	Value Indoor Station: V2.0.0_210120
iVMS-4200 Version	34.0.10 Build201214

New Function

1. Support address book function



2. Support DST function



3. Multi-language support increased to 8 countries: English, Traditional Chinese, Portuguese (Brazil), Russian, Spanish, Turkish, Arabic and Vietnamese

Fix Bugs

1. Fix the problem that iVMS-4200 cannot get the card number

