

KD9203 Firmware V2.2.37_221212 Release Note (2022-12-20)

Device Model	DS-KD9203-E6、 DS-KD9203-FE6、 DS-KD9203-TE6、 DS-KD9203-FTE6
Firmware Version	V2.2.37_221212
iVMS-4200 Version	Late version
Hik-Connect APP	Late version

Fix:

- 1、 Fix known device security vulnerability issues.

KD9203 Firmware V2.2.37_220316 Release Note (2022-03-20)

Device Model	DS-KD9203-E6、 DS-KD9203-FE6、 DS-KD9203-TE6、 DS-KD9203-FTE6
Firmware Version	V2.2.37_220316
iVMS-4200 Version	Late version
Hik-Connect APP	Late version

Fix:

- 2、 Fix the issue that the fails to log in when the language other than English is selected .

KD9203 Firmware V2.2.37_211125 Release Note (2021-11-29)

Device Model	DS-KD9203-E6、 DS-KD9203-FE6、 DS-KD9203-TE6、 DS-KD9203-FTE6
Firmware Version	V2.2.37_211125
iVMS-4200 Version	Late version
Hik-Connect APP	Late version

Fix:**Modified bugs:**


- 1、 When Door Station call Indoor Station by “Outer Door Station” mode (with protocol 2.0), there is no message record in Indoor Station.
- 2、 The device will be rebooted caused by switching Portuguese.

KD9203 Firmware V2.2.37_210812 Release Note (2021-08-12)

Device Model	DS-KD9203-E6、 DS-KD9203-FE6、 DS-KD9203-TE6、 DS-KD9203-FTE6
Firmware Version	V2.2.37_210812
iVMS-4200 Version	Late version
Hik-Connect APP	4.13.1 or above

Modify

1、 HiK-Connect is disabled and Verification code is empty by default.




Face Recognize Door Station Firmware V2.0.0_210120 Release Note (2021-02-01)


Device Model	DS-KD9203-E6、 DS-KD9203-FE6 DS-KD9203-TE6、 DS-KD9203-FTE6
Firmware Version	Value Indoor Station : V2.0.0_210120
iVMS-4200 Version	3.4.0.10 Build201214

New Function

1. Support address book function




2. Support DST function



3. Multi-language support increased to 8 countries: English, Traditional Chinese, Portuguese (Brazil), Russian, Spanish, Turkish, Arabic and Vietnamese

Fix Bugs

1. Fix the problem that iVMS-4200 cannot get the card number



Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com