

## DS-K1T341A Series MinMoe Terminal Release Notes (2022-07-01)

<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF	Firmware Version	ARM: ACS_641_AI3_EN_STD_V3.2.30_build220610 ACS_641_AI3_EN_NEU_V3.2.30_build220610
	SDK	Latest version
<b>Naming Rule:</b> M for M1 card, F for fingerprint	iVMS-4200 Client Version	Latest version baseline

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

### Modified Features

1. Fix the problem that the occasional face recognition frame is stuck
2. Fixed some ISAPI protocol integration issues

## DS-K1T341A Series MinMoe Terminal Release Notes (2022-04-09)

<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF	Firmware Version	ARM: ACS_641_AI3_EN_STD_V3.2.30_build220311 ACS_641_AI3_EN_NEU_V3.2.30_build220311
	SDK	Latest version
<b>Naming Rule:</b> M for M1 card, F for fingerprint	iVMS-4200 Client Version	Latest version baseline

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

### Modified Features

3. Optimize the fingerprint module performance.

## DS-K1T341A Series MinMoe Terminal Release Notes (2022-03-09)

<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF	Firmware Version	ARM: ACS_641_AI3_EN_STD_V3.2.30_build220210 ACS_641_AI3_EN_NEU_V3.2.30_build220210
	SDK	Latest version
<b>Naming Rule:</b> M for M1 card, F for fingerprint	iVMS-4200 Client Version	Latest version baseline

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

### Modified Features

4. Fix the problem that the occasional screen backlight cannot be turned off;

## DS-K1T341A Series MinMoe Terminal Release Notes (2022-02-09)

<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF	Firmware Version	ARM: ACS_641_AI3_EN_STD_V3.2.30_build211229 ACS_641_AI3_EN_NEU_V3.2.30_build211229
	SDK	Latest version
<b>Naming Rule:</b> M for M1 card, F for fingerprint	iVMS-4200 Client Version	Latest version baseline

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

**Modified Features**

5. Fix the issue that the device events exceeds the capability set and the automatic deletion cannot be fully covered;

## DS-K1T341A Series MinMoe Terminal Release Notes (2022-01-04)

<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF  <b>Naming Rule:</b> M for M1 card, F for fingerprint	Firmware Version	ARM: ACS_641_AI3_EN_ <b>STD</b> _V3.2.30_build211223 ACS_641_AI3_EN_ <b>NEU</b> _V3.2.30_build211223
	SDK	Latest version
	iVMS-4200 Client Version	Latest version baseline

**Reason of Upgrade**

Fix bugs, enhance products quality and meet customers' requirements.

**Modified Features**

6. Update the driver to be compatible with the new fingerprint module;

## DS-K1T341A Series MinMoe Terminal Release Notes (2021-12-10)

<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF  <b>Naming Rule:</b> M for M1 card, F for fingerprint	Firmware Version	ARM: ACS_641_AI3_EN_ <b>STD</b> _V3.2.30_build211122 ACS_641_AI3_EN_ <b>NEU</b> _V3.2.30_build211122
	SDK	Latest version
	iVMS-4200 Client Version	Latest version baseline

**Reason of Upgrade**

Fix bugs, enhance products quality and meet customers' requirements.

**Modified Features**

1. Update the driver to be compatible with the new fingerprint module;
2. Optimize ISAPI protocol related functions

## **DS-K1T341A Series MinMoe Terminal Release Notes (2021-11-15)**

<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF	Firmware Version	ARM: ACS_641_AI3_EN_STD_V3.2.30_build211110 ACS_641_AI3_EN_NEU_V3.2.30_build211110
	SDK	Latest version
<b>Naming Rule:</b> M for M1 card, F for fingerprint	iVMS-4200 Client Version	Latest version baseline

**Reason of Upgrade**

Fix bugs, enhance products quality and meet customers' requirements.

**Modified Features**

1. Fix the device offline issue caused by searching device event from iVMS4200 client through ISUP5.0 protocol;
2. Fixed some issues about ISAPI protocol.
3. Optimize the connection with HikCentral Professional platform;

## **DS-K1T341A Series MinMoe Terminal Release Notes (2021-10-18)**

<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF	Firmware Version	ARM: ACS_641_AI3_EN_STD_V3.2.30_build210731 ACS_641_AI3_EN_NEU_V3.2.30_build210731
	SDK	Latest version


<b>Naming Rule:</b> M for M1 card, F for fingerprint	iVMS-4200 Client Version	Latest version baseline
---	-----------------------------	-------------------------

## Reason of Upgrade

Add new function, fix bugs, enhance products quality and meet customers' requirements.


## New Features

1. Add Hik-Connect menu in device UI Menu → Comm. The function is disabled in default.



## Modified Features

1. Optimize the wake-up distance of the device screen through the face, and the wake-up distance is consistent with the recognition distance



## DS-K1T341A Series MinMoe Terminal Release Notes (2021-06-23)

<b>Device Model:</b> DS-K1T341AM	Firmware Version	ARM: ACS_641_AI3_EN_**STD**_V3.2.30_build210609 ACS_641_AI3_EN_**NEU**_V3.2.30_build210609
-------------------------------------	------------------	---

DS-K1T341AMF	SDK	Latest version
<b>Naming Rule:</b> M for M1 card, F for fingerprint	iVMS-4200 Client Version	Latest version baseline

### **Reason of Upgrade**

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

2. Optimize the function of exporting data to U disk.
3. Optimize the working mechanism of infrared supplement light.

### **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)