

Title:	How to Upgrade Hybrid SAN Firmware to V235-2 (via web)	Version:	v1.0	Date:	05/14/2020
Product:	Hybrid SAN			Page:	1 of 4

## Preparation

- The status of Hybrid SAN must be **Working**



- Support V234 and above versions to upgrade, Version below V234 please upgrade to V234-3 first
- V235-2 Firmware  
Please check the capacity of each patch after you download from the FTP.

0astoros-201702271556-C-backup_system-915.bin	2018/12/12 16:29	BIN 文件	61 KB
1astoros-201805081616-B_FW-Multi_V2.28sp2-915.bin	2018/12/12 16:32	BIN 文件	26,663 KB
1bstoros-201808271442-B_FW-Avoid_Dead_2.2-915.bin	2018/12/12 16:33	BIN 文件	8,902 KB
2astoros-201808141848-B_OS_915-storOS_HWT_N25363_CVR235-915.bin	2018/12/12 16:38	BIN 文件	38,711 KB
2bstoros-201803261332-B_OS_915-storOS_page_time_2018-915.bin	2018/12/12 16:38	BIN 文件	53 KB
2cstoros-201808101326-B_OS_915-storOS_switch_open_oversea_mode-915.bin	2018/12/12 16:39	BIN 文件	5,154 KB
3astoros-201808010116-B_SAN-Baseline-915.bin	2018/12/12 16:39	BIN 文件	4,504 KB
3bstoros-201806140823-C_SAN-enable_iscsi_akey_configuration-915.bin	2018/12/12 16:39	BIN 文件	53 KB
3cstoros-201702131218-C_NAS_V130-update_NAS-915.bin	2018/12/12 16:39	BIN 文件	921 KB
4astoros-201604051916-CVR-watchdog2.0-stop-CVR232.bin	2018/12/12 16:39	BIN 文件	56 KB
4bstoros-201808311122-B-CVR_V235_release-suse_x64-91X.bin	2018/12/12 17:01	BIN 文件	45,297 KB
4cstoros-201807050705-C-TO-N+1-CONFIG-FOR_23X-915.bin	2018/12/12 17:01	BIN 文件	204 KB
4dstoros-201808021124-B-cvr_version-suse_x64-91X.bin	2018/12/12 17:01	BIN 文件	52 KB
4estoros-201807311400-Fix-nvr_conf-suse_x64-91X.bin	2018/12/12 17:01	BIN 文件	53 KB


Title:	How to Upgrade Hybrid SAN Firmware to V235-2 (via web)	Version:	v1.0	Date:	05/14/2020
Product:	Hybrid SAN			Page:	2 of 4

## How to Upgrade Hybrid SAN Firmware to V235-2 (via web)


### 1. Upgrade **0astoros-201702271556-C-backup\_system-915**

**Note:**

Please wait several minutes until it shows below tips



2. Upgrade **1astoros-201805081616-B\_FW-Multi\_V2.28sp2-915**
3. Upgrade **1bstoros-201808271442-B\_FW-Avoid\_Dead\_2.2-915**
4. Upgrade **2astoros-201808141848-B\_OS\_915-storOS\_HWT\_N25363\_CVR235-915**
5. Upgrade **2bstoros-201803261332-B\_OS\_915-storOS\_page\_time\_2018-915**
6. Upgrade **2cstoros-201808101326-B\_OS\_915-storOS\_switch\_open\_oversea\_mode-915**
7. Upgrade **3astoros-201808010116-B\_SAN-Baseline-915**
8. Upgrade **3bstoros-201806140823-C\_SAN-enable\_iscsi\_akey\_configuration-915**
9. Upgrade **3cstoros-201702131218-C\_NAS\_V130-update\_NAS-915**
10. Upgrade **4astoros-201604051916-CVR-watchdog2.0-stop-CVR232**
11. Upgrade **4bstoros-201808311122-B-CVR\_V235\_release-suse\_x64-91X**
12. Upgrade **4cstoros-201807050705-C-TO-N+1-CONFIG-FOR\_23X-915**
13. Upgrade **4dstoros-201808021124-B-cvr\_version-suse\_x64-91X**
14. Upgrade **4estoros-201807311400-Fix-nvr\_conf-suse\_x64-91X**
15. Reboot



<b>Title:</b>	How to Upgrade Hybrid SAN Firmware to V235-2 (via web)	<b>Version:</b>	v1.0	<b>Date:</b>	05/14/2020
<b>Product:</b>	Hybrid SAN			<b>Page:</b>	3 of 4

**First Choice for Security Professionals**  
***HIKVISION* Technical Support**



<b>Title:</b>	How to Upgrade Hybrid SAN Firmware to V235-2 (via web)	<b>Version:</b>	v1.0	<b>Date:</b>	05/14/2020
<b>Product:</b>	Hybrid SAN			<b>Page:</b>	4 of 4