| Title: | How to Upgrade Hybrid SAN Firmware to V232-6 (via web) | **Version:** | v1.0 | **Date:** | 04/29/2020 |
|---|---|---|---|---|---|
| **Product:** | Hybrid SAN | | | **Page:** | 1 of 4 |

## Preparation

1. The status of Hybrid SAN must be Working




2. Support V231-4MC versions to upgrade

3. V232-6 Firmware
   Please check the capacity of each patch after you download from the FTP.




© Hangzhou Hikvision Digital Technology Co.,Ltd. All Rights Reserved.
No.555 Qianmo Road, Binjiang District, Hangzhou 310052, China • Tel: +86-571-8807-5998 • Fax: +1 909-595-0788
E-Mail: support@hikvision.com • www.hikvision.com

# How to Upgrade Hybrid SAN Firmware to V232-6（via web）

## 1. Upgrade 1storos-201606141705-B_OS-BiosSize-915

**Note:**

Please wait several minutes until it shows below tips




## 2. Reboot




## 3. Upgrade 2storos-201705091035-C_CVR231-4_CVR232-6-hk9000server316-9_add_upgradeserver-91X

## 4. Upgrade 3storos-201707100859-Multi-CVR-V2.3.2-6_FW_OS_CVR-STD-COSTOM-suse_x64-91X

***Note:***

Please wait several minutes until it shows below tips




© Hangzhou Hikvision Digital Technology Co.,Ltd. All Rights Reserved.
No.555 Qianmo Road, Binjiang District, Hangzhou 310052, China • Tel: +86-571-8807-5998 • Fax: +1 909-595-0788
E-Mail: support@hikvision.com • www.hikvision.com

5. **Upgrade 4storos-201409291645-naz_db_init_CVR_V231-suse_x64-91X**
6. **Reboot**




**First Choice for Security Professionals**
***HIKVISION* Technical Support**

© Hangzhou Hikvision Digital Technology Co.,Ltd. All Rights Reserved.
No.555 Qianmo Road, Binjiang District, Hangzhou 310052, China • Tel: +86-571-8807-5998 • Fax: +1 909-595-0788
E-Mail: support@hikvision.com • www.hikvision.com

© Hangzhou Hikvision Digital Technology Co.,Ltd. All Rights Reserved.
No.555 Qianmo Road, Binjiang District, Hangzhou 310052, China • Tel: +86-571-8807-5998 • Fax: +1 909-595-0788
E-Mail: support@hikvision.com • www.hikvision.com