A8 AcuSense NVR V4.60.105 build220118 Release Notes

(2022-2-1)

Firmware Basic Information	Firmware Version:	V4.60.105 build220118
	SDK Version:	V6.1.7.20_build20210513
	Play Library (PlayCtrl.dll)	V6.0.0.5
	Web version	V4.5.0 build 211229
	Client version	V3.6.5.4 build20210929

Reason of Upgrade

Optimize product performance.

Solved issue

1. POE streaming issue

Solve the issue that POE port 1 cannot connect camera and obtain stream in V4.60.100

Related product list

AcuSense NVR	Overseas:
	DS-9616NXI-I8/S(C)
	DS-9632NXI-I8/S(C)
	DS-9664NXI-I8/S(C)
	DS-7916NXI-I4/S(C)
	DS-7932NXI-I4/S(C)
	DS-7916NXI-I4/16P/S(C)
	DS-7932NXI-I4/16P/S(C)
	DS-7808NXI-I2/S(C)
	DS-7816NXI-I2/S(C)
	DS-7808NXI-I2/8P/S(C)
	DS-7816NXI-I2/16P/S(C)

	DS-7716NXI-I4/S(C)
	DS-7732NXI-I4/S(C)
	DS-7716NXI-I4/16P/S(C)
	DS-7732NXI-I4/16P/S(C)
	DS-7608NXI-I2/S(C)
	DS-7616NXI-I2/S(C)
	DS-7608NXI-I2/8P/S(C)
	DS-7616NXI-I2/16P/S(C)

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:
- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.