Network Video Recorder

Version: V3.4.112 build200604

Release Note

Firmware	Firmware Version:	V3.4.112build200604
Basic Information	Web component:	V4.0.1 build180226

Solved Issue:

1. Solve the issue that the device will reboot when verification code of Hik-Connect is empty.

Related product list:

K series NVR	DS-7600NI-K2(/P)
	DS-7700NI-K4(/P)
	DS-8600NI-K8

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.

- Hikvision doesn't give any guarantee for old models' stock.

- Hikvision is not liable for any typing or printing errors.

- For special model's change details, please contact our local technical support team.