Title:	How to Upgrade Hybrid SAN Firmware to V231-4MC (via web)	**Version:**	v1.0	**Date:**	04/29/2020
Product:	Hybrid SAN			**Page:**	1 of 4

Preparation

1. The status of Hybrid SAN must be Working

2. Support V231-4MA and V231-4MB versions to upgrade

3. V231-4MC Firmware
   Please check the capacity of each patch after you download from the FTP.



© Hangzhou Hikvision Digital Technology Co.,Ltd. All Rights Reserved.
No.555 Qianmo Road, Binjiang District, Hangzhou 310052, China • Tel: +86-571-8807-5998 • Fax: +1 909-595-0788
E-Mail: support@hikvision.com • www.hikvision.com

How to Upgrade Hybrid SAN Firmware to V231-4MC（via web）

1. Upgrade 1storos-201606141705-B_OS-BiosSize-915

Note:

Please wait several minutes until it shows below tips



2. Reboot



3. Upgrade 2storos-201708261446-Multi-CVR_OS_-CVR231-4MC001-suse_x64-91X

Note:

Please wait several minutes until it shows below tips



© Hangzhou Hikvision Digital Technology Co.,Ltd. All Rights Reserved.

No.555 Qianmo Road, Binjiang District, Hangzhou 310052, China • Tel: +86-571-8807-5998 • Fax: +1 909-595-0788
E-Mail: support@hikvision.com • www.hikvision.com

4. Reboot



First Choice for Security Professionals
***HIKVISION* Technical Support**

© Hangzhou Hikvision Digital Technology Co.,Ltd. All Rights Reserved.
No.555 Qianmo Road, Binjiang District, Hangzhou 310052, China • Tel: +86-571-8807-5998 • Fax: +1 909-595-0788
E-Mail: support@hikvision.com • www.hikvision.com

© Hangzhou Hikvision Digital Technology Co.,Ltd. All Rights Reserved.
No.555 Qianmo Road, Binjiang District, Hangzhou 310052, China • Tel: +86-571-8807-5998 • Fax: +1 909-595-0788
E-Mail: support@hikvision.com • www.hikvision.com