H92 AcuSense NVR V4.40.415 Build201112

Release Notes

(2020-11-14)

	Firmware Version:	V4.40.415 Build201112
Firmware Basic Information	SDK Version:	V6.1.4.45_build20200525
	Play Library (PlayCtrl.dll)	V7.3.8.45
	Web version	V4.0.1 build200803
	Client version	V3.3.2.2 build20200728

Reason of Upgrade

Optimize product performance.

Modified functions

- 1. Fix the issue: the time zone information is not completely updated and some related functions are abnormal after modifying the time zone through the Web/ISAPI protocol:
 - After NTP is enabled, it will display the time of original time zone. –There will be a time deviation in the recording video.
 - 2) Linked mail, it will display the time of original time zone.
 - 3) There will be a time zone deviation in RTSP playback positioning time.
 - There will be a time zone deviation in the file name on the CD when backup to it.

Related product list:

AcuSense NVR	Overseas:
	DS-79(08/16/32)NXI-I4/S
	DS-79(08/16/32)NXI-I4/16P/S
	DS-77(08/16/32)NXI-I4/S
	DS-77(08/16/32)NXI-I4/(16P)/S
	DS-76(08/16)NXI-12/S
	DS-78(08/16)NXI-12/S
	DS-7808NXI-I2/8P/S

DS-7608NXI-I2/8P/S
DS-7816NXI-I2/16P/S
DS-7616NXI-I2/16P/S

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect

automatically after upgrading from previous versions. We'd like to inform you the

above changes. Also, we are sorry for any possible inconvenience of use-habit

changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: support@hikvision.com