

## Turbo HD DVR V4.21.100 build200307

### Release Note

<b>Firmware Basic Information</b>  V4.21.000 build 190722	Firmware Version:	V4.21.100 build200307
	SDK Version:	V5.3.6.35_build20180830
	Onvif Version:	V2.2
	Player:	4.8mini
	Play Library (PlayCtrl.dll)	7.3.3.0
	Web component:	V4.0.1build200120 , V3.0.6.46
	IVMS-4200:	V2.6.11.4 build20180831

#### Reason of Upgrade:

Fix some known issues and optimize product stability.

#### New features:

1. Support reset password function by Hikconnect

#### Released product list:

Coaxial-audio models	DS-7104HQHI-K1(S)	DS-7108HQHI-K1(S)	DS-7116HQHI-K1(S)
	DS-7204HQHI-K1(S)	DS-7208HQHI-K1(S)	DS-7208HQHI-K2(S)
	DS-7216HQHI-K1(S)	DS-7216HQHI-K2(S)	DS-7104HUHI-K1(S)
	DS-7108HUHI-K1(S)	DS-7204HUHI-K1(S)	DS-7204HUHI-K2(S)
	DS-7208HUHI-K1(S)	DS-7208HUHI-K2(S)	DS-7216HUHI-K2(S)
	DS-7204HTHI-K1(S)	DS-7204HTHI-K2(S)	DS-7208HTHI-K2(S)

Non coaxial-audio models	DS-7104HQHI-K1	DS-7108HQHI-K1	DS-7116HQHI-K1
	DS-7204HQHI-K1	DS-7208HQHI-K1	DS-7208HQHI-K2
	DS-7216HQHI-K1	DS-7216HQHI-K2	DS-7104HUHI-K1
	DS-7108HUHI-K1	DS-7204HUHI-K1	DS-7204HUHI-K2
	DS-7208HUHI-K1	DS-7208HUHI-K2	DS-7216HUHI-K2
	DS-7204HTHI-K1	DS-7204HTHI-K2	DS-7208HTHI-K2
	DS-7324HQHI-K4	DS-7332HQHI-K4	DS-8124HQHI-K8
	DS-8132HQHI-K8	DS-7224HQHI-K2	DS-7232HQHI-K2
	DS-7304HQHI-K4	DS-7308HQHI-K4	DS-7316HQHI-K4
	DS-8108HQHI-K8	DS-8116HQHI-K8	

## **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

### Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: support@hikvision.com