

Turbo HD DVR V4.26.100 build 210207 Release Notes (2021-02-23)


	Firmware Version:	V4.26.100 build 210207
	SDK Version::	V6.1.6.4_build20200925
Firmware Basic Information	Onvif:	V2.2
	Player:	4.810mini
	Player library:	7.3.5.0
	Web version:	V4.0.1 build 210105
	Client version:	V3.5.0.4E

Reason of Upgrade

 Add some new features, modify some functions, and enhance product quality to meet the customers' requirements.

Main update

- 1. iDS-7204HQHI-M1/S(C) \(iDS-7208HQHI-M1/S(C) \(iDS-7208HQHI-M2/S \) (C) are developed based on new platform
- 2. Due to the resource restriction, the face detection function is removed.
- 3. When enable motion 2.0, the audible warming is disabled as default.





Available Modes:

K20A8	iDS-7204HQHI-M1/S(C)
	iDS-7208HQHI-M1/S(C)
	iDS-7208HQHI-M2/S(C)

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635