

Turbo HD DVR V4.26.120 build 210304 Release Notes

(2021-02-23)

	Firmware Version:	V4.26.120 build 210304
	SDK Version::	V6.1.6.4_build20200925
Firmware	Onvif:	V2.2
	Player:	4.810mini
Basic Information	Player library:	7.3.5.0
	Web version:	V4.0.1 build 210105
	Client version:	V3.5.0.4E

Reason of Upgrade

 Add some new features, modify some functions, and enhance product quality to meet the customers' requirements.

Main update

- iDS-7204HQHI-M1/FA(C),iDS-7208HQHI-M1/FA(C),iDS-7208HQHI-M2/FA(C),iDS-7204HUHI-M1/FA(C),iDS-7204HUHI-M2/FA (C) are developed based on new platform.
- 2. When enable motion 2.0, the audible warming is disabled as default.

Motion	Video Tampering Vi	deo Loss Alarm Input	Alarm Outp	ut Exception		
Camera [A1] Camera 01						
Enable Motion Detection						
Enable Dynamic Analysis for Motion						
Area Settings Arming Schedule Linkage Method						
	ormal Linkage	✓ Trigger Alarm O	utput	Trigger Recording		
🗌 Au	dible Warning			✓ A1		
Send Email				□ A2		
Notify Surveillance Center				□ A3		
Full Screen Monitoring				☐ A4		
Upload Pictures to Cloud						



First Choice for Security Professionals

Available Modes:

K20A8FA	iDS-7204HQHI-M1/FA(C)
	iDS-7208HQHI-M1/FA(C)
	iDS-7208HQHI-M2/FA(C)
	iDS-7204HUHI-M1/FA(C)
	iDS-7204HUHI-M2/FA (C)

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after

upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any

possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310052, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635