# DS-K1T331 Series MinMoe Terminal Release Notes (2020-09-18)

<b>Device Model:</b> DS-K1T331	Firmware Version	ACS_331_AI2_EN_GM_V3.1.4_build200910
DS-K1T331W Naming Rule:	SDK	Latest baseline
W for WIFI	iVMS-4200 Client Version	Latest baseline

## **Reason of Upgrade**

Add new features, fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

- 1. Optimize camera performance and fix occasional screen freeze problem
- 2. Fix the issue that MinMoe device will occasionally restart after being added to the NVR device
- 3. Fix the issue of event loss in ISUP mode
- 4. Other bug fix and enhance user experience

#### **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

#### Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: overseabusiness@hikvision.com