

# DS-K1T331 Series MinMoe Terminal Release Notes (2022-07-01)

Device Model: DS-K1T331	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build220610 ACS_331_AI2_EN_NEU_V3.2.30_build220610
DS-K1T331W	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

1. Fixed some ISAPI protocol integration issues

# DS-K1T331 Series MinMoe Terminal Release Notes (2022-03-09)

Device Model: DS-K1T331	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build220210 ACS_331_AI2_EN_NEU_V3.2.30_build220210
DS-K1T331W	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

2. Fix the problem that the occasional screen backlight cannot be turned off;



### DS-K1T331 Series MinMoe Terminal Release Notes (2022-02-09)

Device Model: DS-K1T331	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build211229 ACS_331_AI2_EN_NEU_V3.2.30_build211229
DS-K1T331W	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

3. Fix the issue that the device events exceeds the capability set and the automatic deletion cannot be fully covered;

# DS-K1T331 Series MinMoe Terminal Release Notes (2021-11-15)

Device Model: DS-K1T331	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build211110 ACS_331_AI2_EN_NEU_V3.2.30_build211110
DS-K1T331W	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Fix bugs, enhance products quality and meet customers' requirements.

#### **Modified Features**

- 1. Fix the device offline issue caused by searching device event from iVMS4200 client through ISUP5.0 protocol;
- 2. Fixed some issues about ISAPI protocol.
- 3. Optimize the connection with HikCentral Professional platform;




## DS-K1T331 Series MinMoe Terminal Release Notes (2021-10-18)


Device Model: DS-K1T331	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build210731 ACS_331_AI2_EN_NEU_V3.2.30_build210731
DS-K1T331W	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

Add new function, fix bugs, enhance products quality and meet customers' requirements.

### **New Features**

1. Add Hik-Connect menu in device UI Menu→Comm. The function is disabled in default.






### **Modified Features**

1. Optimize the wake-up distance of the device screen through the face, and the wake-up distance is consistent with the recognition distance





### DS-K1T331 Series MinMoe Terminal Release Notes (2021-06-23)

Device Model: DS-K1T331	Firmware Version	ACS_331_AI2_EN_STD_V3.2.30_build210609 ACS_331_AI2_EN_NEU_V3.2.30_build210609
DS-K1T331W	SDK	Latest baseline
Naming Rule: W for WIFI	iVMS-4200 Client Version	Latest baseline

#### **Reason of Upgrade**

Fix bugs, enhance products quality and meet customers' requirements.

#### **Modified Features**

- 2. Optimize the function of exporting data to U disk.
- 3. Optimize the working mechanism of infrared supplement light.

#### **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

#### Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.



Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,

China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com