

## DS-K1T341A Series MinMoe Terminal Release Notes (2020-10-16)


<b>Device Model:</b> DS-K1T341AM DS-K1T341AMF  <b>Naming Rule:</b> M for M1 card, F for fingerprint	Firmware Version	ACS_641_AI3_EN_GM_V3.1.7_build200927
	SDK	Latest version
	iVMS-4200 Client Version	Latest version baseline

### Reason of Upgrade

Add new features, fix bugs, enhance products quality and meet customers' requirements.

### New Features

1. Support one key call Hik-Connect mobile App



### Modified Features

1. Fix the display problem of web multilingual translation;
2. Fix ISUP5.0 event upload problem
3. Fix the problem of fingerprint enrollment in web

## **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)