



iVMS-4200 AC V1.7.1

Release Notes

Legal Information

© 2022 Hangzhou Hikvision Digital Technology Co., Ltd. All rights reserved.

This Document (hereinafter referred to be “the Document”) is the property of Hangzhou Hikvision Digital Technology Co., Ltd. or its affiliates (hereinafter referred to as “Hikvision”), and it cannot be reproduced, changed, translated, or distributed, partially or wholly, by any means, without the prior written permission of Hikvision. Unless otherwise expressly stated herein, Hikvision does not make any warranties, guarantees or representations, express or implied, regarding to the Document, any information contained herein.

About this Document

Pictures, charts, images and all other information hereinafter are for description and explanation only. The information contained in the Document is subject to change, without notice, due to updates or other reasons.

Please use this Document with the guidance and assistance of professionals trained in supporting the Product.

LEGAL DISCLAIMER

TO THE MAXIMUM EXTENT PERMITTED BY APPLICABLE LAW, THE DOCUMENT IS PROVIDED "AS IS" AND "WITH ALL FAULTS AND ERRORS". HIKVISION MAKES NO REPRESENTATIONS OR WARRANTIES, EXPRESS OR IMPLIED, INCLUDING BUT NOT LIMITED TO, WARRANTIES OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE OR NON-INFRINGEMENT. IN NO EVENT WILL HIKVISION BE LIABLE FOR ANY SPECIAL, CONSEQUENTIAL, INCIDENTAL, OR INDIRECT DAMAGES INCLUDING, AMONG OTHERS, DAMAGES FOR LOSS OF BUSINESS PROFITS, BUSINESS INTERRUPTION, OR LOSS OF DATA, CORRUPTION OF SYSTEMS, OR LOSS OF DOCUMENTATION, WHETHER BASED ON BREACH OF CONTRACT, TORT (INCLUDING NEGLIGENCE), OR OTHERWISE, IN CONNECTION WITH THE USE OF THE DOCUMENT, EVEN IF HIKVISION HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES OR LOSS.

TABLE OF CONTENTS

Chapter 1 Introduction	1
1.1 Overview	1
1.2 Version	1
1.3 Components	1
Chapter 2 What's New	2
2.1 Person Management	2
2.1.1 Added Feature	2
2.2 Device Management	2
2.2.1 Updated Feature	2
Chapter 3 Resolved Issues	3

Chapter 1 Introduction

1.1 Overview

iVMS-4200 AC Client software is designed to configure and manage Hikvision devices in a unified and intuitive manner, including video intercom devices and access control devices.

The software provides multiple functionalities including person management, access control, video intercom, time & attendance, etc.

1.2 Version

Version	Date
iVMS-4200 AC V1.7.1	2022-03

1.3 Components

Component	Version	Date of Release	Latest Version or Not
Network SDK	V6.1.9.10	2022-03-04	Yes
ISUP SDK	V4.2.7.0	2022-03-09	Yes

Chapter 2 What's New

2.1 Person Management

2.1.1 Added Feature

The supported model of card enrollment station: DS-K1F100A-D8E.

2.2 Device Management

2.2.1 Updated Feature

The supported number of elevator controllers: 4 (for overseas version), 64 (for domestic version).

Chapter 3 Resolved Issues

The following are issues resolved in this version.

No.	Issue Description
1	Error occurred when getting events of access control terminals, prompting that the device is offline or network timeout.
2	After the Client applies the permission to the elevator controller, the elevator controllers on some floors failed to apply the fingerprints collected via the card reader.
3	When face recognition terminal in the thermography mode, the Client did not display the captured picture for the temperature screening event.
4	Error occurred when opening doors remotely after an access controller was added to the Client via ISAPI protocol.
5	Error occurred during the card reader authentication after an access controller was added to the Client via ISUP protocol.
6	When uploading a picture of a local person, no picture will be displayed.
7	After collecting face via the access control device, applying the face picture failed.
8	Face picture size exceeds the limit, resulting in the failure of applying face picture.
9	Error occurred during the statistics of working time on workday and weekend in the monthly report.
10	Importing CSV file for the attendance event failed.
11	The preview of monthly attendance report is inconsistent with the exported data.
12	Unreadable code occurred during person name synchronization in the third-party attendance database.
13	Jumping to the remote configuration page failed for some non-video devices.



See Far, Go Further