

# Temperature Screening MinMoe Terminal

## Release Notes (2020-10-15)

<b>Device Model:</b> DS-K1T671TM-3XF DS-K1TA70MI-T DS-K5671-3XF DS-K5604A-3XF	Firmware Version	<b>ARM:</b> ACS_671_3XF_AI3_EN_GM_V2.2.6_build200927 <b>Thermal Module:</b> digicap_thermo-en-gm_V.5.4_build200807
	SDK	HCNetSDKV6.1.4.151_build20200601_win32_ZH HCISUPSDKV2.3.5.152_build20200518_Win32_ZH
	iVMS-4200 Version	iVMS-4200 AC(V1.2.50.8_E).exe

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

### Modified Features

1. Optimize the performance of the camera and temperature screening module, fix the occasional screen freeze problem.
2. Fixed the web login problem of thermal module
3. Optimize related content in the open source statement

### Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

#### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: support@hikvision.com