

Network Video Recorder

Version: V4.32.110 build211009

Release Note

Firmware Basic Information	Firmware Version:	V4.32.110 build211009
	SDK Version:	V6.1.4.20_build20200320_Win32_ZH
	Play Library:	7.3.8.45
	Web component:	V4.0.1build210914
	OpenSDK Version:	V2.7.0 build 201014


Reason of Upgrade


Add new features and optimize product performance.

New features

1. 【Buzzer linkage optimization】


- 1) If the device has not received or recognized the hard disk, no hard disk, hard disk error, abnormal recording alarm, etc. will not be triggered.
- 2) When the recording plan is opened, the channel is added, and the hard disk has been identified, the recording abnormal alarm will be triggered, otherwise the alarm will not be triggered.
- 3) The event alarm does not link the buzzer by default.
- 4) Maintenance-in more, add buzzer one-key switch.





2. 【Added privacy prompts on GUI and web activation and login interface】

1) GUI



2) Web



Modified functions

Related product list:



First Choice for Security Professionals

71Q series NVR	DS-7104NI-Q1 (C), DS-7104NI-Q1/4P (C) DS-7104NI-Q1/M(C), DS-7104NI-Q1/4P/M (C) DS-7108NI-Q1 (C), DS-7108NI-Q1/8P (C) DS-7108NI-Q1/M (C), DS-7108NI-Q1/8P/M (C)
----------------	---

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.