

## Network Video Recorder

**Version: V4.40.017 build 201124**

### Release Note

**(2020-11-24)**

<b>Firmware Basic Information</b>	Firmware Version:	V4.40.017 build201124
	SDK Version:	V6.1.4.40_build20200428
	Play Library:	V7.3.8.45
	Web component:	V4.0.1 build200611
	OpenSDK Version:	V2.4.0

### Reason of Upgrade

Fix some issues and optimize product performance.

---

## **Fixed issue**

Fix the problem of abnormal NVR system time caused by changing the NVR time zone and then turning on NTP timing function.

## **Related product list:**

I series NVR	DS-9600NI-I16, DS-9600NI-I8 DS-8600NI-I8, DS-7700NI-I4(B)/(P) DS-7600NI-I2(/P)
--------------	--

## **Customer Impact and Recommended Action**

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

### Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.