

Network Video Recorder

Version: V3.4.103 build181226

Release Note

(2018-12-26 External)

	Firmware Version:	V3.4.103 build181226
Firmware	SDK Version:	V5.3.6.40
Basic Information	SADP:	3.0.0.21
	Web Component:	V4.0.1build181011

Reason of Upgrade

Fix some issues for better performances on E series NVR.

Solve the issue

1. [HDD]

(1) Solve the issue that starting time is too long.

2. [web display]

(1) Solve the issue that the web items display imcompletely when use some languages, for example, Japanese.

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

