

H8_V5.8.5 Release Note

(2023-07-16)

Firmware Basic Information	Firmware Version: V5.8.5 build230530
---	--------------------------------------

Features

New function

- Added smart pan-tilt correction models
- Fixed bugs

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action.

For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
 No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
 China
 Tel: +86-571-8807-5998
 FAX: +86-571-8993-5635
 Email: overseabusiness@hikvision.com

Supported models		
Product series	Smart Pan-Tilt Correction	Product models
PTZ Cameras	Y	DS-2DF8A442IXG-F/SP
PTZ Cameras	Y	DS-2DF8A442IXG-EL
PTZ Cameras	Y	DS-2DF8A442IXG-ELY
PTZ Cameras	Y	DS-2DF8A842IXG-EL
PTZ Cameras	Y	DS-2DF8A442NXG-EL
PTZ Cameras	N/A	DS-2DF8442IXG-ELY
PTZ Cameras	N/A	DS-2DF8442IXG-ELWY
PTZ Cameras	N/A	DS-2DF8442IXG-ELW
PTZ Cameras	N/A	DS-2DF8442IXG-EL
PTZ Cameras	N/A	DS-2DF8C442IXG-EL
PTZ Cameras	N/A	DS-2DF8242IXG-ELW
PTZ Cameras	N/A	DS-2DF8242IXG-EL
PTZ Cameras	N/A	DS-2DF8242I5XG-ELW
PTZ Cameras	N/A	DS-2DF6A436XG-ELY
PTZ Cameras	N/A	DS-2DF6A436XG-EL

PTZ Cameras

N/A

DS-2DF8C442IXG-ELW