

PTZ/Network Camera Firmware Version: V5.7.9

Release Note

(2022-05-20)

Firmware Basic Information	Firmware Version:	IPD_H8_EN_STD_V5.7.9 build 220520
	SDK Version:	V6.1.4.20_build20201112
	iVMS-4200:	V3.4.2.1 build20210105
	Web version:	V4.0.1.0build210524

Camera Features

1. New Features

- Newly release the below models:

DS-2DF8C425MHS-DEL/ DS-2DF8C425MHS-DELW

DS-2DF8C435MHS-DEL/ DS-2DF8C435MHS-DELW

DS-2DF8C835MHS-DEL/ DS-2DF8C835MHS-DELW

2. Improved Features

- DF camera supports sound and light alert function
- Fix some known bugs

3. Leftover Issues

- N/A

Compatibility Update

- Tested NVRs:

DS-9664NI-I16(B) V4.51.105 build 211027

DS-7604NXI-Q1/S V3.4.97_171031 V4.31.105 build 210727

Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou
310051, China
Tel: +86-571-8807-5998