

Turbo HD DVR V4.26.131 build 210811 Release Notes (2021-08-12)

Firmware Basic Information	Firmware Version:	V4.26.131 build 210811
	SDK Version:	V6.1.4.20 build 20200320
	Onvif:	V2.2
	Player:	4.810mini
	Player library:	7.3.5.0
	Web version:	V4.0.1 build 210105
	Client version:	V2.6.13.0 build 20181115

Reason of Upgrade

- Add some new functions, modify some functions, and enhance product quality to meet customers' requirements.

Fixed issues

1. Playback on Hik-Connect, there is no video bar, and the video will appear after the video bar is moved to the time after 9 o'clock.
2. The motion defense plan configured on the web client is invalid.
3. The MAC address is refreshed after the device parameter file is imported.
4. The M-series DVR still uploads alarm after one-key disarming function is enabled.

Available Modes:

K20A7	iDS-7204HQHI-M1/S(C) iDS-7204HQHI-M1/S(C)
DVR-K20A8FA	iDS-7208HQHI-M2/FA (C) iDS-7208HQHI-M1/FA (C) iDS-7204HQHI-M1/FA (C) iDS-7204HUHI-M1/FA (C) iDS-7204HUHI-M2/FA (C)
K20A8	iDS-7208HQHI-M2/S/(C) iDS-7208HQHI-M1/S/(C)

	iDS-7204HUHI-M2/S/(C) iDS-7204HUHI-M1/S/(C)
K8A3FA	iDS-7208HUHI-M1/FA iDS-7208HUHI-M2/FA iDS-7216HQHI-M1/FA iDS-7216HQHI-M2/FA iDS-7208HQHI-M2/FA
K8A3	iDS-7208HUHI-M1/S iDS-7208HUHI-M2/S iDS-7216HQHI-M1/S iDS-7216HQHI-M2/S

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

For questions or concerns, please contact our local technical support team.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310052,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: support@hikvision.com