

# KV9 Villa Door Station V2.3.5\_build230328 Release Note (2023-04-18)

## **Firmware Basic Information**

Firmware	Firmware Version	V2.3.5_build230328
Basic	Device Type	DS-KV9503-WBE1
Information		

### Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

### **Modified Features**

1. Solved the very small probability of startup failure.

Note: This issue in previous version can be solved by disconnecting the power and powering up again.

## KV9 Villa Door Station V2.3.5\_build221230 Release Note (2023-01-05)

## Firmware Basic Information

Firmware	Firmware Version	V2.3.5_build221230
Basic	Device Type	DS-KV9503-WBE1
Information		

## Reason of Upgrade

Fix bugs, enhance products quality and meet customers' requirements.

#### **Modified Features**

2. Fix known device security vulnerability issues.

# KV9 Villa Door Station V2.3.5\_build221031 Release Note (2022-11-05)



## **Firmware Basic Information**

Firmware	Firmware Version	V2.3.5_build221031
Basic	Device Type	DS-KV9503-WBE1
Information		

## Reason of Upgrade


New model DS-KV9503-WBE1 villa door station first time released.






## **New Features**

- 1. 4.3 inch colorful IPS touch screen, 2 MP wide-angle dual-lens HD camera with WDR feature;
- 2. Higher protection level, IP65 & IK08
- 3. Multiple authentication methods: card, face, PIN code and QR code, (only support QR code generated from HikCentral visitor module)
- 4. Internal Mifare card reader, 1 physical button to call Indoor station/Center
- 5. Standard PoE or 12 VDC power supply
- 6. Up to 20,000 contacts, 20,000 faces, 100,000 card can be added to the device




7. Brand new web5.0 interface






8. If device and mobile phone are in same network, you can login device mobile web from browser. Note: Not support deleting face picture in mobile web interface, you can only add or modify.



9. Support internal SADP function, you can search devices in same network, select device and add to door station directly.

Note: You can't see the devices which has same ip address as the villa door station






#### 10. Support contact function


Note: The device will have different UI interface display depending on the number of indoor units added.

1) If added indoor station quantity is less than 4 (include 4), the user will show as nametag.




2) If added indoor station quantity is more than 5 (include 5), the user will show as contact list. Or you can also switch to keypad mode to input room number manually.






11. Support linking indoor station to room number with letters, then you can dial the linked room number in keypad mode.





- 12. Support Bluetooth function which allows you to open door from mobile phone APP (this function will be available in future firmware and APP version)
- 13. Support 3<sup>rd</sup> stream with H.265 decoding format while the main and sub stream are still H.264 format





14. Wi-Fi module has 2 modes, Wi-Fi mode or AP mode. You can change it from web interface Note: if you enable hotspot mode, the Wi-Fi will disconnect.








15. Support 2 modes for main interface (live view mode or custom mode), if you select custom mode, it will not display when you verify with face.




16. Enable or disable QR/Face verification and Call Center short cut key function from web or local menu.



17. Support call schedule for the physical call button







## **Notice**

We strongly recommend updating the door stations to latest baseline firmware



## **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

#### Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China

Tel: +86-571-8807-5998 FAX: +86-571-8993-5635

Email: overseabusiness@hikvision.com

\_