

# DS-K1T642 Series MinMoe Terminal

## Release Notes (2020-06-22)


<b>Device Model:</b> DS-K1T642M DS-K1T642E DS-K1T642MF DS-K1T642EF DS-K1T642MW DS-K1T642EW DS-K1T642MFW DS-K1T642EFW  <b>Naming Rule:</b> M for M1 card, E for EM card, F for fingerprint, W for Wi-Fi	Firmware Version	<b>ARM:</b> ACS_641_AI3_EN_GM_V3.1.7_build200616 <b>MCU:</b> ACS_DS-K1T64X_ST1_GML_GM_V1.0.0_build200606_Mifare ACS_DS-K1T64X_ST1_GML_GM_V1.0.0_build200606_EM
	SDK	Latest baseline version
	iVMS-4200 Version	iVMS-4200 AC(V1.0.3.16_E) or later

### Reason of Upgrade


Fix bugs, enhance products quality and meet customers' requirements.

### New Features

1. Add face mask detection function(enabled in default);



2. Support English, Thai, Russian, Spanish, Arabic, Indonesian and Vietnamese languages;



## **Customer Impact and Recommended Action**

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

Note:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,  
China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)