

Thermographic Temperature Screening Handheld Camera DS-2TP31B-3AUF

Version:V5.4.38 build200922

Release Notes

(2020-11-11)



Firmware VersionV5.4.38 build 200922Product Support ListDS-2TP31B-3AUF

Reason of Upgrade

Added new features and implemented some optimizations.

New Features

 Supported multiple languages (English, Russian, German, Italian, French, Spanish, Korean, Hungarian, Czech, Slovak, Polish, Portuguese, Romanian, Danish, Turkish, Japanese and Traditional Chinese) on the user interface.

Optimization

- Added background temperature compensation algorithm. Improved the temperature measurement accuracy when the device is used in environment background with high temperature (like 35°C in a tent).
- 2. Added temperature drift suppression algorithm. Improved the stability of temperature measurement and fixed issues of noise in thermal image during cold booting.
- 3. Added Sensor ID info. in Device Information.
- 4. Fixed display abnormality of battery icon in some cases.



Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd. No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China Tel: +86-571-8807-5998 FAX: +86-571-8993-5635 Email: overseabusiness@hikvision.com